

Date: Thursday, 01/05/2008 7:22:25 AM
 User: Melanie Fauteux

Process Sheet

Customer	: CC-DAR01 Dart Aerospace Ltd.	Drawing Name	: D350-616-013
Job Number	: 38914		
Estimate Number	: 10804		
P.O. Number	:	Part Number	: D350616013
This Issue	: 01/05/2008 S.O. No. :	Drawing Number	: NCR08-041
Prsht Rev.	: NC	Project Number	:
First Issue	: / / Type : SMALL /MED FAB	Drawing Revision	:
Previous Run	: 00015	Material	:
Written By	:	Due Date	: 07/05/2008 Qty: (4) Um: Each
Checked & Approved By	:		
Comment	:		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	QC	QUALITY CONTROL
-----	----	-----------------



Comment: QUALITY CONTROL

Quarantine all D350-616-013 is stock.

B	19404	Qty:	1X
B	32507	Qty:	1
B	37350	Qty:	2
B		Qty:	
B		Qty:	

8/5/1 sep 4X

2.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Pick the following items to add to the D350-616-015 kits, inside the D350-616-013 kits.

3.0	AN960JD10	Washer
-----	-----------	--------



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Washer

M10715

4.0	MS35207264	Screw
-----	------------	-------



Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s)

Screw

M11599

5.0	QC4	INSPECT 100% KITS FOR COMPLETENESS
-----	-----	------------------------------------



Comment: INSPECT 100% KITS FOR COMPLETENESS

8/5/1 sep 4X

Date: Thursday, 01/05/2008 7:22:25 AM
User: Melanie Fauteux

Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D350-616-013

Job Number: 38914

Part Number: D350616013

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

PACKAGING 1

PACKAGING RESOURCE #1



(4/x)

Comment: PACKAGING RESOURCE #1

Re-package the D350-616-013, and return to stock using the same batch #'s.

Location: 28

Rec

8/5/1

SL

7.0

QC21

FINAL INSPECTION/W/O RELEASE



08/05/05

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



MF 08-05-01